

JRMEC™
ENGINEERING

This chart shows the 129 distinct adjustment positions available with the R-37 prosthetic alignment device. The reference view is from the foot toward the socket, with the toes positioned at the front and the heel at the back. Use this chart in conjunction with the positioning illustration on the next page to determine the correct product orientation and adjustment locations.

This positioning illustration defines the orientation used for the supplied positioning chart. The reference view is from the foot toward the socket, with the toes positioned at the front and the heel at the back. To use the supplied positioning chart, install the device as shown in this illustration with letter "M" toward the toe and letter "E" toward the heel.

